
VAN ASSELT SCHOOL ADDITION /

Seattle Landmark Preservation Board Architectural Review Committee Meeting

March 12, 2021



SELECTED OPTION - SITE PLAN



1909 BUILDING - SUMMARY


- -Exterior Scope of Work
- -Interior Scope of Work





WINDOWS





VANDAL PROOF METAL MESH





Window Restoration Scope of Work:

- -Removing or encapsulating asbestos containing glazing putty
- -Painting exterior frames and sashes (color TBD)
- -Replacing hardware or fixing window sash in place
- -Replacing broken glazing with in-kind material
- -Adding new weather stripping
- -Removing and patching surface rot
- -Replacing rotten wood members for windows with structural deficiencies
- -Finish touch up on the inside frame, sashes, and wood trim
- -Obscure glazing at basement floor windows at the south and southeast facade (looking into the boiler room).
- -Install vandal proof metal mesh at all basement floor windows (interior side) except for south basement level windows.



EXTERIOR ENVELOPE



Exterior Envelope Scope of Work:


- -Patching or replacing damaged wood siding with in kind material.
- -Repainting siding, fascia boards, and wood trim (color TBD).
- -Repainting concrete foundation walls (color TBD).
- -Replacing exterior doors to match original panel and half-light; Providing hardware per district standards.
- -Removing (3) exterior modern light fixtures (flood lights) from the face of the building.
- -Preserving existing sign 'Van Asselt Public School'.



EAST ELEVATION



SYSTEMS APPROACH - CLASSROOMS



SYSTEMS APPROACH - CLASSROOMS



NORTH ELEVATION



EAST ELEVATION





SOUTH ELEVATION WEST ELEVATION



SYSTEMS APPROACH - CLASSROOMS










RADIATOR





CONCEPT RENDERING OF RESTORED CLASSROOM

Classroom Scope of Work

Architectural:

- -Retain, patch and repair original materials, where possible, at walls and floors.
- -Remove existing ceiling tiles and plaster; replace with new drywall and acoustic treatment.
- -Patch and paint plaster walls, and previously painted wood trim and plaster molding.
- -New marker boards installed on top of existing chalkboards at teaching wall.

Structural:

-Minor seismic upgrades at wall to floor connections.

Electrical:

- -Install new light fixtures
- -Install new power and data
- -Install new projector at teaching wall
- -Route electrical systems through wall/ceiling cavities where practical; some exposed systems may be required.


Mechanical:

- -New ventilation grills located at top of west wall.
- -New radiator located at east wall below the window sills.
- -New ducts located in Support space.
- -Sprinkler system to be exposed at ceiling.






SYSTEMS APPROACH - MAIN STAIR



VAN ASSELT SCHOOL ADDITION /

SYSTEMS APPROACH - MAIN STAIR



NORTH ELEVATION



EAST ELEVATION



SOUTH ELEVATION

WEST ELEVATION



SYSTEMS APPROACH - MAIN STAIR STRUCTURAL SHEAR WALLS AT SECOND AND THIRD FLOOR DN UP **ENTRY** STAIR LOBBY **LOBBY** UP DN **NEW FIRE RATED** DOOR AT ALL SCHOOL HOUSE **LOCATION** LIGHT FIXTURES MECHANICAL **SOFFIT ABOVE** (ONLY THIS LEVEL)

Main Stair Scope of Work

Architectural:

- -Retain, patch and repair original material at walls, floor, and ceiling.
- -Detail guardrail/handrail to meet code requirements (detail TBD).

Structural:

-Add seismic shear wall at portions of north and south walls; provide new plaster to match existing where plaster is removed.

Electrical:

- -Provide new light fixtures.
- -Route electrical systems through wall/ceiling cavities where practical; some exposed systems may be required.

Mechanical:

-New duct routing will require soffit at west wall.




LANDSCAPE DESIGN REVIEW

- -Site Plan General Scope of Work
- -Planting Design at East Plaza
- -Paving Design at East Plaza






SITE PLAN - GENERAL SCOPE OF WORK




EAST PLAZA - PLANTING



Planting Scope of Work

General Notes:

- -Species are selected for specific site conditions (shade to sun dependent on location).
- -Species within bioretention planting areas are selected for their seasonal tolerance of both wet and dry conditions.
- -Planting options need to be reviewed and approved by SPS.





Asarum caudatum/ Wild Ginger





Mahonia nervosa/ Low Oregon Grape



BPA - Deep to Part Shade

Spiraea betulifolia/ Birch-Leaf Spiraea



Oxalis oregona 'Klamath Ruby'



Acorus gramineus 'Ogon'/ Sweetflag



Polystichum munitum/ Sword Fern



BPA - Full to Part Sun

Itea virgnica 'Little Henry'/ Sweetspire



Physocarpus opulifolius 'Little Devil'/ Ninebark






Gingko biloba 'Autumn Gold'/ Autumn Gold Gingko





EAST PLAZA - PAVING



-Paving options need to be reviewed and approved by SPS.





EXTERIOR OPTIONS REVIEW

- -Color Analysis
- -Exterior Materials
- -3 Color Options





ELEVATIONS - COLOR ANALYSIS



PATROPS UNACCE B-43
F-4709
7201-BEACON A

VAN ASSELT SCHOOL CIRCA 1940

EXISTING MATERIALS & COLORS



DETAILS



OBSERVED ORIGINAL COLORS




SW 7547 Sand Bar




Note: Paint swatch colors as appearing on this page can vary














THANK YOU!



